

Polo Classic

Confusion

Case Study

By: Tamas Krasznai
2013.01.17

Vw Polo Classic 1,6 AKL Engine code




The error

- The engine will not start
- If it starts it goes well for a while then stops
- DTC: camshaft position sensor
crankshaft position sensor
engine coolant temperature sensor
throttle position sensor
short circuit to positive


Starting the investigation

© all rights reserved




L	L1	ohm	
570	24	900	


USEING PICO







Krasznai Autódiagnosztika Kft.





2in 1







K K r a s z n a i A u t ó d i a g n o s z t i k a K f t .




K K r a s z n a i A u t ó d i a g n o s z t i k a K f t .

This is where it got wet




Krasznai Autódiagnosztika Kft.

This is where it got wet



The solution: change ECU





Krasznai Autódiagnosztika Kft.

