



Name	Channel	Scope	Value
Frequency	D	Whole trace	35.8 Hz
Frequency	D	Between rulers	35.8 Hz

21-Oct-06 17:41:05

"Measurements" defect: there are 34+ intervals over 1.0 seconds. "Frequency" over "Whole trace" ought to be just over 34 per second, Not almost 36 per second.

"Frequency" "Between rulers" is also incorrect. Either it is not implemented or it is being miscalculated.

	1	2	Δ	$1/\Delta$
Time Axis	17.09ms	980.5ms	963.5ms	1.038 Hz
Channel A	75.0mV	823.0mV	748.0mV	