

Shop Name: T.A.R. Diagnostic Inc.

Tel: 1 (246) 622-1481

Email: tardagnosticinc@outlook.com

Address: Lot 4M1
Lower Estate
St. Michael

Vehicle information

BMW 2011_05 1'116i_N45

VIN: WBAUE1201CP244657

Diagnostics time: 2018/05/02 14:52

Mileage:**Path:** Automatic selection > Diagnosis > Auto scan > Live data >
Valve gear >

Valve gear

NO.	Name	Value	Unit
1	Adaptation value, camshaft, exhaust	-4.45	°
2	Adaptation value, camshaft, inlet	-4.45	°
3	Camshaft position, exhaust	247.90	°
4	Camshaft position, inlet	656.90	°
5	VANOS position, exhaust	109.30	°
6	VANOS exhaust spread, setpoint value	109.60	°
7	VANOS position, inlet	130.00	°
8	VANOS inlet spread, setpoint value	130.40	°